


STRUCTURE STABILITY CERTIFICATE


This is to certify that the Block-1, Block -2 & Block 3 (all four storied) Buildings of Sacred Heart Convent School at Dhalli, Shimla, are safe.

I have inspected the buildings on 21-03-2020 and found safe. The Structure satisfy the safety requirement as stipulated under Para 5.0.1 (Building Bye Laws-Structure Design). The Structure is safe for habitation.

1. Signature of Owner/
Authorised Signatory with date  21/03/2020


Name in block letters SR. LATITIA CARDOZA

Address SACRED HEART CONVENT SCHOOL
FLEUR-DE-LYS, DHALLI, SHIMLA-17
BELOW SABJI MANDI, SAKIJAULI.

2. Signature of Architect with date  21/03/2020


Name in block letters Sanjeev Building

Address Sanjauli Mandi

3. Signature of Structure Engineer with date  21/03/2020

Name in block letters Sanjeev Building

Address Sanjauli Mandi


PRINCIPAL
Sacred Heart Convent
Fleur-de-lys, Dhalli
Shimla-171012